

# Building Report - Jobs Done – From AGM2012 to AGM2013

Compiled by Garry Glaves and Drew Pearce with thanks to all our invaluable helpers

## Ski Room

Seat cut back to allow drying room door to open fully

## Entry

External light over entry door

Rubber mat inside and outside (outside covering metal step – bound to old mats for stability)

Waterproof torch mounted on elastic cord outside (emergency light for entering door code)

## Wood Room

Two deliveries stacked

## Workshop

No work

## Laundry

New fluro light

Clothes dryer mounted on wall

## Drying Room

New fluro light

## Lounge Room

Power point installed at end of dining table (for the IT members and guests)

Heat bank fans replaced

Window sill at end of dining table removed

## Kitchen

Worn power points replaced

Faulty stove repaired. (wiring chewed bare by small furry house guests)

Rubbish bin lid repair

## Hallway

No work

## Bathroom

New tap washers in both bathrooms

New tap handles in ladies large shower

## Bedrooms

Two window winders replaced

## Building

Entry door replaced

Games exit door replaced

Remaining faces of the chimney ground out and grouted

Rugby building name repair

Back door lock is dodgy (top floor near men's bathroom)

## Exterior

Grass slashing around building

Skylight waterproof plastic sheeting re-sealed (one missing)

Waste box to suit NPWS specifications

## Coming up

Complete Waste Box and deliver